

FIG. 1




FIG. 1




FIG. 3




FIG. 2

FOOT T302000T




FIG. 4




FIG. 5

FIG. 10




FIG. 6




FIG. 9

FIG. 7





FIG. 8






FIG. 13




FIG. 11








FIG. 12



170




FIG. 20

FIG. 18





FIG. 19




FIG. 21




FIG. 22A




FIG. 22B

FIG. 22B




FIG. 23

FIG. 24A




FIG. 24B




FIG. 24C





FIG. 24D






FIG. 28




FIG. 27




FIG. 25




FIG. 26




Fig. 29




FIG. 30




FIG 31




FIG. 32

10007064-4304
F002 F0502000

FIG. 33










FIG. 33

FIG. 34



100075040001

Pressure



Time

Fig. 39

FOOT - 1000

Pressure





FIG. 40

Time

FOOT - 1000

Pressure



Time

FIG. 41

FOOT - 1902000

Pressure




Fig. 42

Time

Pressure
FOOT = 1902000





FIG. 43

TOEFT T002000T

Pressure




Time

FIG. 44

10007051-13001

Pressure



Time

FIG. 45

Pressure






FIG 46

FOOT "T50/0000" Pressure



FOOT-TSODT-1007051-113001

Pressure



Time

FIG. 48

Pressure




FIG. 49

Time

10007061-13004

Pressure




FIG. 50

Time

FOOT-F902000F

Pressure




FIG. 51

Time

100067051-113001

Pressure




FIG. 52

Time

10007061-113004

Pressure




FIG 53

Time

Pressure




FIG. 54

Time